

AIA Document G710™ - 1992

Architect's Supplemental Instructions

PROJECT (Name and address):
SMCCD - Canada College Bldg 8
4220 Farm Hill Boulevard
Redwood City, CA 94061

ARCHITECT'S SUPPLEMENTAL
INSTRUCTION NO: 006

OWNER (Name and address):
San Mateo Community College
District
3401 CSM Drive
San Mateo, CA 94402

DATE OF ISSUANCE: November 06, 2008

CONTRACT FOR: General Construction

FROM ARCHITECT (Name and
address):
Bunton Clifford Associates
License No. C01859
210 Hammond Avenue
Fremont, CA 94539

CONTRACT DATE: October 01, 2007

TO CONTRACTOR (Name and
address):

ARCHITECT'S PROJECT NUMBER: 07014
DSA File No. 41-C1 DSA APPL No. 01-
109554

Schembri Construction Co., Inc.
1485 Bayshore Blvd. # 130
San Francisco, CA 94124

The Work shall be carried out in accordance with the following supplemental instructions issued in accordance with the Contract Documents without change in Contract Sum or Contract Time. Proceeding with the Work in accordance with these instructions indicates your acknowledgment that there will be no change in the Contract Sum or Contract Time.

DESCRIPTION:

In response to RFI 20.1:

- * Please refer to the attached response from Interface Engineering for insulation requirements for below grade insulated piping at wall penetration.
- * Please refer to the attached response from Rinne Peterson Structural Engineers for requirements of the (2) 8" water pipes cores.

ATTACHMENTS:

(Here insert listing of documents that support description.)

- RFI 20.1 response from Interface engineering dated 09-11-08
- PSK-A dated 06/14/08
- PSK-B dated 06/14/08
- RFI 20.1 response from Rinne Peterson Structural Engineers dated 11-06-08
- SK-2 dated 9/9/08
- Structural calculations dated 11/5/08

- OWNER:
- ARCHITECT:
- CONSULTANT:
- CONTRACTOR:
- FIELD:
- OTHER:

AIA Document G710™ - 1992. Copyright © 1979 and 1992 by The American Institute of Architects. All rights reserved. WARNING: This AIA® Document is protected by U.S. Copyright Law and International Treaties. Unauthorized reproduction or distribution of this AIA® Document, or any portion of it, may result in severe civil and criminal penalties, and will be prosecuted to the maximum extent possible under the law. This document was produced by AIA software at 15:54:45 on 11/08/2008 under Order No. 1000371682_4 which expires on 10/3/2009, and is not for resale. User Notes:

(3000148432)

5106223073