

Construction Progress Photos











Building 22



























































Cañada Exterior Furniture





Cañada Smart Classroom





Cañada Smart Classroom





Infrastructure

New Boiler Room Pumps





Exterior Lights





Exterior Lights





Cañada Summer Paving





Cañada Summer Paving





CSM Summer Paving





CSM CDC Site Improvements





CSM CDC Site Improvements





CSM CDC Site Improvements





CSM CDC Site Improvements






CSM Gym Asbestos Abatement for new lighting



CSM Gym Lighting





CSM Gym Lighting





CSM Exterior Lights





Skyline Energy Efficiency

Co-Generation Pad





Skyline Energy Efficiency

Co-Generation Unit





Skyline

Energy Efficiency

Co-Gen Exhaust Stack Enclosure





Energy Efficiency

New Boiler Room Pumps





Skyline Pumps

Infrastructure Upgrades





Skyline Energy Efficiency

New Boiler Room Pumps





Skyline – Energy Efficiency New Boiler Room Pumps





Infrastructure Upgrades

Bldg# 1 Drain Installation





Infrastructure Upgrades

Bldg #5 Trench Drain





Infrastructure Upgrades

Bldg #5 Trench Drain





Skyline
Infrastructure
Upgrades

Bldg# 1 New Drains





Infrastructure Upgrades

Repair of Drain at Track





Skyline Summer Paving Perimeter Road






Summer Paving

Parking Lot #6





Skyline Summer Paving Sidewalk Repair





Skyline Summer Paving Exterior Light Project








Skyline Summer Paving Exterior Light Project







Skyline Summer Paving Exterior Light Project







